




COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. :
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	20/CAF/PCH/XII/GAP/2023
	Jakarta	CIF No.: 012/WEB/XII/2023
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/23/2050	
Quality Order	60.000 KG	Product : HVS
Quality Complaint	530 KG	Specification : HVS ROLL 80 82 PPLUS
Problem : -FLUI		
Category of Complaint ☒ Quality ☐ Packaging ☐ Delivery ☐ Ect		Claim value (IDR/USD/SGD/EUR) : In Words (Tujuh juta duaratus enam puluh satu ribu rupiah)
Data : ☐ Original sample / before process ☐ Sample after process ☐ Comparison sample ☐ Inspection Card ☐ Ream Label ☐ Ect ☐ Copy of DN ☒ Photo ☐ Packaging ☐ Pull Tape (for Picking / Dusting problem)		
Notes : NO ID ROLL : 213392989 NO.DO 5782038283		
Jakarta, 26 Desember 2023		
Prepared by, 26-12-2023  (Gita Siti) (Staff Pembelian)	Checked by, 26-12-2023  (Maurina Gurning) (Ka. Bag. Pembelian)	Approved by, (.....) (Supplier)