



COMPLAINT ASSESSMENT FORM

Supplier Name	Budi Karya Sentosa Sejati	Complaint No. :
Address	Perum Candragaba AP 5 No.26 RT. 27 RW 19 Bahagia Babelan Jawa Barat	11/CAF/PCH/III/GAP/2024
	Bekasi	CIF No.: 003/FIN/III/2024
Phone	021-8583386	
PIC	Budi Santoso	Invoice No. :
PO	PO/23/2064	
Quality Order	5 roll	Product : 5 ROLL
Quality Complaint	5 roll	Specification : PLASTIK LAMGLS 18MCX62X4000BKS

Problem :

PLASTIK 62 GLOSSY : Lengket sebanyak 3 roll Buram sebanyak 1 roll Bergelombang sebanyak 1 roll

Kategori of Complaint

☒ Quality☐ Packaging☐ Delivery☐ Ect☐ Handling☐ Quantity

Claim value (IDR/USD/SGD/EUR) :

In Words

(.....)

Data :

☐ Original sample / before process☐ Sample after process☐ Comparison sample☐ Inspection Card☐ Ream Label☐ Ect☐ Copy of DN☒ Photo☐ Packaging☐ Pull Tape (for Picking / Dusting problem)

Notes :

1 PLASTIK 62 GLOSSY 1 ROLL (32,90 kg) Lengket 2 PLASTIK 62 GLOSSY 1 ROLL (35,10 kg) Lengket 3 PLASTIK 62 GLOSSY 1 ROLL (36,05 kg) Lengket 4 PLASTIK 62 GLOSSY 1 ROLL (24,10 kg) Buram 5 PLASTIK 62 GLOSSY 1 ROLL (31,80 kg) Bergelombang

Jakarta, 15 Maret 2024

Prepared by,
15-03-2024Checked by,
16-03-2024Approved by,
17-03-2024(Nurul)
(Staff Pembelian)(Maurina Gurning)
(Ka. Bag. Pembelian)(Aris Budi)
(Supplier)