



COMPLAINT ASSESSMENT FORM

Supplier Name	Budi Karya Sentosa Sejati	Complaint No. :
Address	Perum Candragaba AP 5 No.26 RT. 27 RW 19 Bahagia Babelan Jawa Barat	12/CAF/PCH/III/GAP/2024
	Bekasi	CIF No.: 004/FIN/III/2024
Phone	021-8583386	
PIC	Budi Santoso	Invoice No. :
PO	PO/23/2064	
Quality Order	5 roll	Product : 5 ROLL
Quality Complaint	5 roll	Specification : PLASTIK LAMGLS 18MCX45X4000BKS

Problem :

Lengket sebanyak 5 roll

Kategori of Complaint

☒ Quality☐ Handling☐ Packaging☐ Quantity☐ Delivery☐ Ect

Claim value (IDR/USD/SGD/EUR) :

In Words

(.....)

Data :

☐ Original sample / before process☐ Copy of DN☐ Sample after process☒ Photo☐ Comparison sample☐ Packaging☐ Inspection Card☐ Pull Tape (for Picking / Dusting problem)☐ Ream Label☐ Ect

Notes :

1. PLASTIK 45 GLOSSY 1 ROLL (25,30 Kg) Lengket 2. PLASTIK 45 GLOSSY 1 ROLL (23,50 Kg) Lengket 3. PLASTIK 45 GLOSSY 1 ROLL (23,95 Kg) Lengket 4. PLASTIK 45 GLOSSY 1 ROLL (24,95 Kg) Lengket 5. PLASTIK 45 GLOSSY 1 ROLL (29,15 Kg) Lengket

Jakarta, 15 Maret 2024

Prepared by,
15-03-2024Checked by,
16-03-2024Approved by,
17-03-2024(Nurul)
(Staff Pembelian)(Maurina Gurning)
(Ka. Bag. Pembelian)(Aris Budi)
(Supplier)