



COMPLAINT ASSESSMENT FORM

Supplier Name	Budi Karya Sentosa Sejati	Complaint No. :
Address	Perum Candragaba AP 5 No.26 RT. 27 RW 19 Bahagia Babelan Jawa Barat	13/CAF/PCH/III/GAP/2024
	Bekasi	CIF No.: 005/FIN/III/2024
Phone	021-8583386	
PIC	Budi Santoso	Invoice No. :
PO	PO/23/1988	
Quality Order	12 roll	Product : 2 ROLL
Quality Complaint	2 roll	Specification : PLASTIK LAMDOF 18MCX62X4000BKS

Problem :

Daya rekat kurang (hasil cetakan terangkat)

Kategori of Complaint

- | | |
|---|-----------------------------------|
| ☒ Quality | ☐ Handling |
| ☐ Packaging | ☐ Quantity |
| ☐ Delivery | |
| ☐ Ect | |

Claim value (IDR/USD/SGD/EUR) :
In Words

(.....)

Data :

- | | |
|---|--|
| ☐ Original sample / before process | ☐ Copy of DN |
| ☐ Sample after process | ☒ Photo |
| ☐ Comparison sample | ☐ Packaging |
| ☐ Inspection Card | ☐ Pull Tape (for Picking / Dusting problem) |
| ☐ Ream Label | |
| ☐ Ect | |

Notes :

1. PLASTIK 62 DOFF 1 ROLL (28,50 Kg) Kurang rekat (hasil cetakan terangkat) 2. PLASTIK 62 DOFF 1 ROLL (25,80 Kg) Kurang rekat (hasil cetakan terangkat)

Jakarta, 15 Maret 2024

Prepared by,
15-03-2024Checked by,
16-03-2024Approved by,
17-03-2024(Nurul)
(Staff Pembelian)(Maurina Gurning)
(Ka. Bag. Pembelian)(Aris Budi)
(Supplier)