



COMPLAINT ASSESSMENT FORM

Supplier Name	Cinjoejaya Perkasamuda	Complaint No. :
Address	JL Bandengan Selatan No 60C Jakarta 14440	17/CAF/PCH/IV/GAP/2024
	Jakarta	CIF No.: 010/WEB/IV/2024
Phone	021-6616041-45	
PIC	Ali Gunawan	Invoice No. :
PO	PO/23/1226	
Quality Order	2000000 KG	Product : HVS ROLL
Quality Complaint	486	Specification : HVS ROLL 70 73 RAP PREMIUM

Problem :

-CORE RUSAK (PEYANG)

Kategory of Complaint

☒ Quality☐ Packaging☐ Delivery☐ Ect☐ Handling☐ Quantity

Claim value (IDR/USD/SGD/EUR) :

In Words

(Enam juta dua ratus dua puluh ribu delapan ratus rupiah)

Data :

☐ Original sample / before process☐ Sample after process☐ Comparison sample☐ Inspection Card☐ Ream Label☐ Ect☐ Copy of DN☒ Photo☐ Packaging☐ Pull Tape (for Picking / Dusting problem)

Notes :

ID ROLL 3143350386, NO.DO SJ23036/18822 TGL 20/12/2024

Jakarta, 25 April 2024

Prepared by,
25-04-2024(Gita Siti)
(Staff Pembelian)Checked by,
25-04-2024(Maurina Gurning)
(Ka. Bag. Pembelian)Approved by,
25-04-2024(PT.CINJOE JAYA)
(Supplier)