



COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. :
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	12/CAF/PCH/VI/GAP/2025
	Jakarta	CIF No.: 006/WEB/VI/2025
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/24/2216	
Quality Order	30000000 KG	Product : HVS ROLL
Quality Complaint	571	Specification : HVS ROLL 70 73 AQNA

Problem :

PEANG DAN FLUI

Category of Complaint	Claim value (IDR/USD/SGD/EUR) :
☒ Quality	In Words
☐ Packaging	
☐ Delivery	(Enam juta lima ratus enam puluh enam
☐ Ect	ribu lima ratus rupiah)


Data :

☒ Original sample / before process	☐ Copy of DN
☐ Sample after process	☒ Photo
☐ Comparison sample	☐ Packaging
☐ Inspection Card	☐ Pull Tape (for Picking / Dusting problem)
☐ Ream Label	
☐ Ect	

Notes :

NOMOR ID ROLL QTY KET' RUSAK 300810548 239 FLUI 300811420 332 PEANG NO.DO 5782235540

Jakarta, 04 Juni 2025

Prepared by, 04-06-2025	Checked by, 04-06-2025	Approved by,
		
(Gita Siti) (Staff Pembelian)	(Maurina Gurning) (Ka. Bag. Pembelian)	(.....) (Supplier)