



COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. :
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	20/CAF/PCH/VI/GAP/2025
	Jakarta	CIF No.: 013/WEB/VI/2025
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/25/0475	
Quality Order	3.000.000 KG	Product : HVS ROLL
Quality Complaint	1474.2	Specification : HVS ROLL 70 73 AQNA

Problem :

-CORE KENDOR

Category of Complaint

- ☒ Quality
☐ Packaging
☐ Delivery

- ☐ Handling
☐ Quantity

☐ Ect

Claim value (IDR/USD/SGD/EUR) :

In Words

(Enam belas juta sembilan ratus lima
puluh tiga ribu tiga ratus rupiah)

Data :

- | | |
|--|--|
| ☒ Original sample / before process | ☐ Copy of DN |
| ☐ Sample after process | ☒ Photo |
| ☐ Comparison sample | ☐ Packaging |
| ☐ Inspection Card | ☐ Pull Tape (for Picking / Dusting problem) |
| ☐ Ream Label | |
| ☐ Ect | |

Notes :

NOMOR ID ROLL QTY KET' RUSAK 213902656 491.40 CORE KENDOR 300780713 491.40 CORE KENDOR 300780633 491.40 CORE KENDOR NO.DO 5782269395,5782272762,5782272762

Jakarta, 23 Juni 2025

Prepared by,
23-06-2025

Checked by,
23-06-2025

Approved by,

(.....)

(Gita Siti)
(Staff Pembelian)

(Maurina Gurning)
(Ka. Bag. Pembelian)

(Supplier)