



COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. :
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	21/CAF/PCH/VI/GAP/2025
	Jakarta	CIF No.: 014/WEB/VI/2025
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/25/0475	
Quality Order	3.000.000 KG	Product : HVS ROLL
Quality Complaint	982.78 KG	Specification : HVS ROLL 70 73 AQNA

Problem :

-CORE KENDOR

Category of Complaint

- | | |
|---|-----------------------------------|
| ☒ Quality | ☐ Handling |
| ☐ Packaging | ☐ Quantity |
| ☐ Delivery | |
| ☐ Ect | |

Claim value (IDR/USD/SGD/EUR) :

In Words

(Sebelas Juta tiga ratus satu ribu
sembilan ratus tujuh puluh rupiah)

Data :

- | | |
|--|--|
| ☒ Original sample / before process | ☐ Copy of DN |
| ☐ Sample after process | ☒ Photo |
| ☐ Comparison sample | ☐ Packaging |
| ☐ Inspection Card | ☐ Pull Tape (for Picking / Dusting problem) |
| ☐ Ream Label | |
| ☐ Ect | |

Notes :

NOMOR ID ROLL QTY KET' RUSAK 300781009 491.39 KG CORE KENDOR 30078114 491.39 KG CORE KENDOR NO.DO 5782272767

Jakarta, 25 Juni 2025

Prepared by,
25-06-2025(Gita Siti)
(Staff Pembelian)Checked by,
25-06-2025(Maurina Gurning)
(Ka. Bag. Pembelian)Approved by,
10-07-2025(Oscar)
(Supplier)