



COMPLAINT ASSESSMENT FORM

Supplier Name	Budi Karya Sentosa Sejati	Complaint No. :
Address	Perum Candragaba AP 5 No.26 RT. 27 RW 19 Bahagia Babelan Jawa Barat	27/CAF/PCH/VII/GAP/2025
	Bekasi	CIF No.: 003/SHT/VII/2025
Phone	021-8583386	
PIC	Budi Santoso	Invoice No. :
PO	PO/25/0832	
Quality Order	10 RIM	Product : 10 RIM
Quality Complaint	10 RIM	Specification : PLASTIK PET 200 MICX 100 X 70 CM

Problem :

SURFACE TENSION KERTASNYA DI BAWAH 38, SEHINGGA TIDAK BAIK UNTUK DI CETAK


Category of Complaint	Claim value (IDR/USD/SGD/EUR) :
☒ Quality	In Words
☐ Packaging	
☐ Delivery	(.....)
☐ Ect	

Data :

☐ Original sample / before process	☐ Copy of DN
☐ Sample after process	☒ Photo
☐ Comparison sample	☐ Packaging
☐ Inspection Card	☐ Pull Tape (for Picking / Dusting problem)
☐ Ream Label	
☐ Ect	

Notes :

Jakarta, 29 Juli 2025

Prepared by, 29-07-2025	Checked by, 29-07-2025	Approved by,
		
(Nurul) (Staff Pembelian)	(Maurina Gurning) (Ka. Bag. Pembelian)	(.....) (Supplier)