



COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. :
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	09/CAF/PCH/IV/GAP/2023
	Jakarta	CIF No.: 003/SHT/IV/2023
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/22/1884	
Quality Order	10000 RIM	Product : HVS SHEET
Quality Complaint	36,16 RIM	Specification : HVS 70 56X88 PAPER PINDO PLUS

Problem :

KERTAS LEMBAB, MENYEBABKAN FLUI SAAT PROSES CETAK

Category of Complaint

- ☒ Quality
☐ Packaging
☐ Delivery

- ☐ Handling
☐ Quantity

☐ Ect

Claim value (IDR/USD/SGD/EUR) :
In Words

(Delapan Juta enam ratus empat puluh
empat ribu dua ratus dua puluh delapan
rupiah)

Data :

- | | |
|---|--|
| ☐ Original sample / before process | ☐ Copy of DN |
| ☒ Sample after process | ☒ Photo |
| ☐ Comparison sample | ☐ Packaging |
| ☐ Inspection Card | ☐ Pull Tape (for Picking / Dusting problem) |
| ☐ Ream Label | |
| ☐ Ect | |

Notes :

Jakarta, 19 April 2023

Prepared by,
19-04-2023(Gita Siti)
(Staff Pembelian)Checked by,
19-04-2023(Maurina Gurning)
(Ka. Bag. Pembelian)

Approved by,

(.....)

(Supplier)