PT. GELORA AKSARA PRATAMA
Jl. H. Baping Raya No. 100, Ciracas, Pasar Rebo, Jakarta timur. Telp (021) 8710060. Fax (021) 8710566

COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. : 20/CAF/PCH/XII/GAP/2023
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	
	Jakarta	CIF No.: 012/WEB/XII/2023
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/23/2050	
Quality Order	60.000 KG	Product : HVS
Quality Complaint	530 KG	Specification : HVS ROLL 80 82 PPLUS

Problem :

-FLUI

Kategory of Complaint

- ☑ Quality
- ☐ Handling
- ☐ Packaging
- ☐ Quantity
- ☐ Delivery
- ☐ Ect .....

Claim value (IDR/USD/SGD/EUR) :
Rp. 7.261.000.-
In Words
(Tujuh juta duaratus enam puluh satu ribu rupiah)

Data :

- ☐ Original sample / before process
- ☐ Sample after process
- ☐ Comparison sample
- ☐ Inspection Card
- ☐ Ream Label
- ☐ Ect
- ☐ Copy of DN
- ☑ Photo
- ☐ Packaging
- ☐ Pull Tape (for Picking / Dusting problem)

Notes :

NO ID ROLL : 213392989
NO.DO 5782038283

Jakarta, 26 Desember 2023

Prepared by,	Checked by,	Approved by,
26-12-2023	26-12-2023	
(Gita Siti)	(Maurina Gurning)	(.....)
(Staff Pembelian)	(Ka. Bag. Pembelian)	(Supplier)