PT. GELORA AKSARA PRATAMA
Jl. H. Baping Raya No. 100, Ciracas, Pasar Rebo, Jakarta timur. Telp (021) 8710060. Fax (021) 8710566

COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. : 12/CAF/PCH/VI/GAP/2025
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	
	Jakarta	CIF No.: 006/WEB/VI/2025
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/24/2216	
Quality Order	30000000 KG	Product : HVS ROLL
Quality Complaint	571	Specification : HVS ROLL 70 73 AQNA

Problem :

PEANG DAN FLUI

Kategory of Complaint

- ☑ Quality
- ☐ Handling
- ☐ Packaging
- ☐ Quantity
- ☐ Delivery
- ☐ Ect .....

Claim value (IDR/USD/SGD/EUR) :
Rp.6.566.500
In Words
(Enam juta lima ratus enam puluh enam ribu lima ratus rupiah)

Data :

- ☑ Original sample / before process
- ☐ Sample after process
- ☐ Comparison sample
- ☐ Inspection Card
- ☐ Ream Label
- ☐ Ect
- ☐ Copy of DN
- ☑ Photo
- ☐ Packaging
- ☐ Pull Tape (for Picking / Dusting problem)

Notes :

```
NOMOR ID ROLL QTY KET' RUSAK
300810548 239 FLUI
300811420 332 PEANG

NO.DO 5782235540
```

Jakarta, 04 Juni 2025

Prepared by,	Checked by,	Approved by,
04-06-2025	04-06-2025	
(Gita Siti)	(Maurina Gurning)	(.....)
(Staff Pembelian)	(Ka. Bag. Pembelian)	(Supplier)