



COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. : 15/CAF/PCH/VI/GAP/2025
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor, Jakarta	CIF No.: 007/WEB/VI/2025
Phone	021-3929266-69	Invoice No. :
PIC	Oscar / Oktavina	
PO	PO/25/0670	
Quality Order	500000 KG	Product : HVS ROLL
Quality Complaint	559 KG	Specification : HVS ROLL 70 82 PAPER PINDOPLUS



Problem :
-FLUI

Category of Complaint <input checked="" type="checkbox"/> Quality <input type="checkbox"/> Packaging <input type="checkbox"/> Delivery <input type="checkbox"/> Ect	<input type="checkbox"/> Handling <input type="checkbox"/> Quantity	Claim value (IDR/USD/SGD/EUR) : Rp. 6.708.000.- In Words (Enam juta tujuh ratus delapan ribu rupiah.)
--	--	---

Data : <input checked="" type="checkbox"/> Original sample / before process <input type="checkbox"/> Sample after process <input type="checkbox"/> Comparison sample <input type="checkbox"/> Inspection Card <input type="checkbox"/> Ream Label <input type="checkbox"/> Ect	<input type="checkbox"/> Copy of DN <input checked="" type="checkbox"/> Photo <input type="checkbox"/> Packaging <input type="checkbox"/> Pull Tape (for Picking / Dusting problem)
---	--

Notes :
 NO ID ROLL: 082501023P 559 KG FLUI / BERGELOMBANG
 NO.DO D1L0075387

Jakarta, 18 Juni 2025

Prepared by, 18-06-2025  (Gita Siti) (Staff Pembelian)	Checked by, 18-06-2025  (Maurina Gurning) (Ka. Bag. Pembelian)	Approved by, (.....) (Supplier)
--	---	---