PT. GELORA AKSARA PRATAMA
Jl. H. Baping Raya No. 100, Ciracas, Pasar Rebo, Jakarta timur. Telp (021) 8710060. Fax (021) 8710566

COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. : 20/CAF/PCH/VI/GAP/2025
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	
	Jakarta	CIF No.: 013/WEB/VI/2025
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/25/0475	
Quality Order	3.000.000 KG	Product : HVS ROLL
Quality Complaint	1474.2	Specification : HVS ROLL 70 73 AQNA

Problem :

-CORE KENDOR

Kategory of Complaint

- ☑ Quality
- ☐ Handling
- ☐ Packaging
- ☐ Quantity
- ☐ Delivery
- ☐ Ect .....

Claim value (IDR/USD/SGD/EUR) :
Rp. 16.953.300
In Words
(Enam belas juta sembilan ratus lima puluh tiga ribu tiga ratus rupiah)

Data :

- ☑ Original sample / before process
- ☐ Copy of DN
- ☐ Sample after process
- ☑ Photo
- ☐ Comparison sample
- ☐ Packaging
- ☐ Inspection Card
- ☐ Pull Tape (for Picking / Dusting problem)
- ☐ Ream Label
- ☐ Ect

Notes :

```
NOMOR ID ROLL QTY KET' RUSAK
213902656 491.40 CORE KENDOR
300780713 491.40 CORE KENDOR
300780633 491.40 CORE KENDOR

NO.DO 5782269395,5782272762,5782272762
```

Jakarta, 23 Juni 2025

Prepared by,	Checked by,	Approved by,
23-06-2025	23-06-2025	
(Gita Siti)	(Maurina Gurning)	(.....)
(Staff Pembelian)	(Ka. Bag. Pembelian)	(Supplier)