



COMPLAINT ASSESSMENT FORM

Supplier Name	Budi Karya Sentosa Sejati	Complaint No. : 27/CAF/PCH/VII/GAP/2025
Address	Perum Candragaba AP 5 No.26 RT. 27 RW 19 Bahagia Babelan Jawa Barat	
	Bekasi	CIF No.: 003/SHT/VII/2025
Phone	021-8583386	Invoice No. :
PIC	Budi Santoso	
PO	PO/25/0832	
Quality Order	10 RIM	Product : 10 RIM
Quality Complaint	10 RIM	Specification : PLASTIK PET 200 MICX 100 X 70 CM

Problem :  

SURFACE TENSION KERTASNYA DI BAWAH 38, SEHINGGA TIDAK BAIK UNTUK DI CETAK



<b>Category of Complaint</b> <input checked="" type="checkbox"/> Quality <input type="checkbox"/> Packaging <input type="checkbox"/> Delivery <input type="checkbox"/> Ect .....	<input type="checkbox"/> Handling <input type="checkbox"/> Quantity	<b>Claim value (IDR/USD/SGD/EUR) :</b> In Words ( .CAF ditolak vendor karena material tidak bermasalah perlu punya mesin pemanas. Stok sementara dikembalikan ke gudang. )
--	--	--

**Data :**

<input type="checkbox"/> Original sample / before process	<input type="checkbox"/> Copy of DN
<input type="checkbox"/> Sample after process	<input checked="" type="checkbox"/> Photo
<input type="checkbox"/> Comparison sample	<input type="checkbox"/> Packaging
<input type="checkbox"/> Inspection Card	<input type="checkbox"/> Pull Tape ( for Picking / Dusting problem )
<input type="checkbox"/> Ream Label	
<input type="checkbox"/> Ect	

**Notes :**

**Jakarta, 29 Juli 2025**

Prepared by, 29-07-2025  ( Nurul ) ( Staff Pembelian )	Checked by, 29-07-2025  ( Maurina Gurning ) ( Ka. Bag. Pembelian )	Approved by,  ( ..... ) ( Supplier )
--	---	---