PT. GELORA AKSARA PRATAMA
Jl. H. Baping Raya No. 100, Ciracas, Pasar Rebo, Jakarta timur. Telp (021) 8710060. Fax (021) 8710566

COMPLAINT ASSESSMENT FORM

Supplier Name	Cakrawala Mega Indah	Complaint No. : 51/CAF/PCH/XII/GAP/2025
Address	JL MH Thamrin N, Bii plaza, Tower II 18 th floor,	
	Jakarta	CIF No.: 020/WEB/XII/2025
Phone	021-3929266-69	
PIC	Oscar / Oktavina	Invoice No. :
PO	PO/25/1753	
Quality Order	750.000 KG	Product : HVS ROLL
Quality Complaint	1.003 kg	Specification : HVS ROLL 70 88 AQNA

Problem :

-FLUI

Kategory of Complaint

- ☑ Quality
- ☐ Handling
- ☐ Packaging
- ☐ Quantity
- ☐ Delivery
- ☐ Ect .....

Claim value (IDR/USD/SGD/EUR) :
Rp. 11.333.900.-
In Words
(Sebelas juta tiga ratus tiga puluh tiga ribu sembilan ratus rupiah)

Data :

- ☑ Original sample / before process
- ☐ Copy of DN
- ☐ Sample after process
- ☑ Photo
- ☐ Comparison sample
- ☐ Packaging
- ☐ Inspection Card
- ☐ Pull Tape (for Picking / Dusting problem)
- ☐ Ream Label
- ☐ Ect

Notes :

```
NOMOR ID ROLL QTY KET' RUSAK
214184425 534 FLUI
214184438 469 FLUI
NO.DO 5782320984
```

Jakarta, 26 Januari 2026

Prepared by,	Checked by,	Approved by,
26-01-2026	26-01-2026	
(Gita Siti)	(Maurina Gurning)	(.....)
(Staff Pembelian)	(Ka. Bag. Pembelian)	(Supplier)